

User manual


9102000409

axessline Cable Management


Outlet - 2 Power 1 Data 2 USB-A Charger, black

- 1** CUTOUT
Make the necessary cutout in desk top or partition wall:
217 x 63 mm. Note that additional customized cut-out
might be needed for cables.

- 2** ADJUST (OPTIONAL)
Consider adjusting the side brackets to obtain best results.
Four different positions can be achieved by unscrewing and
re-mounting side brackets. Two of which
are illustrated.




- 4** CONNECT
Connect cables to corresponding external components.



- 3a** MOUNTING (ALTERNATIVE 1)
Mount to wall using 4 screws (not included).
By flipping side brackets upside-down, they can
remain hidden behind the screen (see step **2**).



- 3b** MOUNTING (ALTERNATIVE 2)
Mount to wall using 4 screws (not included).
By flipping side brackets upside-down, they can
remain hidden beneath the table (see step **2**).



Accessories:
Wieland ↔ Schuko
2.0 m 9202002009
3.0 m 9202003009
5.0 m 9202005009

WIELAND GST1813S Female type
Part no 92.931.3053.1
VDE Approval no. 40018414

Cable cord specification
H05VV-F according to EN 50525-2-11
minimum 3 x 1,5 mm